

Fine Aggregate Gradations

Sieve Size Percent Passing

GRAD NO	3/8	NO. 4	NO. 8	NO. 10	NO. 16	NO. 30	NO. 40	NO. 50	NO. 80	NO. 100	NO. 200
FA 1	100	97 +/- 3			65 +/- 20			16 +/- 13		5 +/- 5	
FA 2	100	97 +/- 3			65 +/- 20			20 +/- 10		5 +/- 5	
FA 3	100	97 +/- 3		80 +/- 15			50 +/- 20		25 +/- 15		3 +/- 3
FA 4	100				5 +/- 5						
FA 5	100	92 +/- 8								20 +/- 20	15 +/- 15
FA 6		92 +/- 8								20 +/- 20	6 +/- 6
FA 7		100		97 +/- 3			75 +/- 15		35 +/- 15		3 +/- 3
FA 8			100				60 +/- 20			3 +/- 3	2 +/- 2
FA 9			100					30 +/- 16		5 +/- 5	
FA 10				100			90 +/- 10		60 +/- 30		7 +/- 7
FA 20	100	97 +/- 3	80 +/- 20		50 +/- 15			19 +/- 11		10 +/- 7	4 +/- 4
FA 21	100	97 +/- 3	80 +/- 20		57 +/- 18			30 +/- 10		20 +/- 10	9 +/- 9
FA 22	100	92 +/- 8	42 +/- 10		8 +/- 8						2 +/- 2